


SUBJECT: Pre-programmed Fuel Injection Control Module (FICM) for Navistar® applications

Installing a pre-programmed FICM on an engine that does not have a current ECM calibration or matching reference number could cause catastrophic engine failure. If assistance is needed to verify ECM calibration status, please contact Technical Support at 800.735.9775.

When ordering a FICM, supplying the ECM reference number is required and can be located under the 'vehicle information' tab (image shown on right) in [ServiceMaxx™](#).

Specific ECM programming reference numbers can be found in the table below.

For more information, refer to [NPA 01/20](#).



AP part number	ECM reference number	Year range	Application
AP65126	ANZKHA03	2004-2006	I6
AP65127	ANZKLA03	2004-2006	
AP65128	ANZNHA04	2004-2006	
AP65129	ANZNHB00	2004-2006	
AP65130	ANZNLA04	2004-2006	
AP65131	AQZ0AT04	2006-2009	V6
AP65132	AHZ7AI07	2002-2006	V8
AP65133	ANZ7BJ05	2002-2006	
AP65134	ANZ7BJ07	2002-2006	
AP65135	ANZ7BJ10	2002-2006	

For more information visit

AlliantPower.com